

# Inspection Photos

API: 055-06142

Operator: CAPTUREPOINT LLC

Inspection Date: 6/8/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06142 | Date: 6/8/2023

## Inspection Photos



**Photo 1.** Facing north along the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle  
Yellow arrow → Houndstongue



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06142 | Date: 6/8/2023

## Inspection Photos



**Photo 2.** Facing northeast toward the multi well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06142 | Date: 6/8/2023

## Inspection Photos



**Photo 3.** Well sign is posted at the well head and has been updated with current operator INFO.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06142 | Date: 6/8/2023

## Inspection Photos



**Photo 4.** Facing toward the north side of the location. There are noxious weeds along the north side of the location that need to be controlled. Red arrow → Musk thistle



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06142 | Date: 6/8/2023