

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

01/31/2022

Document Number:

402942931

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10352 Contact Person: Jacob Harter
Company Name: CM PRODUCTION LLC Phone: (970) 946-3761
Address: 390 UNION BLVD SUITE 620 Fax: ()
City: LAKEWOOD State: CO Zip: 80228 Email: jharter@cottonwoodconsulting.com

Identification Information

API Number: 05 - 057-06070 OGCC Facility ID: 212177 Initial Form 19 or 27 Document number: 402725107
Facility Name: SPAULDING, MARGARET (OWP) Facility Number: 8 Facility Type: WELL
Location QtrQtr: NWSE Section: 28 Township: 9N Range: 81W Meridian:
County: JACKSON Field Name: LONE PINE
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CM PRODUCTION LLC Agent Name: Jacob Harter Title: Consultant
Phone Number: 970-946-3761 Email: jharter@cottonwoodconsulting.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 212177 Facility Name: SPAULDING, MARGARET (OWP) 8 Facility Type:
Location: QtrQtr: NWSE Sec: 28 Twp: 9N Range: 81W Meridian: 6
County Name: JACKSON Latitude: 40.722103 Longitude: -106.496571

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 95137 Document Name: Size of file in bytes: 98816 File Name: Spaulding, Margaret 8 Water Sample (2).xls
SampleType: Matrix:
Facility ID: 212177 Sample ID: 632141 Sample Name: Spaulding, Margaret 8 WS02 Sample Date: 09/01/2021
Collection Point: Soil Matrix: WATER Pre Post: Remediation
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2109055-02

Batch ID: 95131		Document Name: Size of file in bytes: 93696		File Name: Spaulding, Margaret 8 Soil Sample (1).xls	
SampleType: _____			Matrix: _____		
Facility ID: 212177	Sample ID: 632135	Sample Name: Spaulding, Margaret 8 SS01		Sample Date: 09/01/2021	
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2109055-03		

Batch ID: 95134		Document Name: Size of file in bytes: 95232		File Name: Spaulding, Margaret 8 Soil Sample (4).xls	
SampleType: _____			Matrix: _____		
Facility ID: 212177	Sample ID: 632138	Sample Name: Spaulding, Margaret 8 SS04		Sample Date: 09/01/2021	
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2109055-06		

Batch ID: 95135		Document Name: Size of file in bytes: 95232		File Name: Spaulding, Margaret 8 Soil Sample (5).xls	
SampleType: _____			Matrix: _____		
Facility ID: 212177	Sample ID: 632139	Sample Name: Spaulding, Margaret 8 SS05		Sample Date: 09/01/2021	
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2109055-07		

Batch ID: 95136		Document Name: Size of file in bytes: 100864		File Name: Spaulding, Margaret 8 Water Sample (1).xls	
SampleType: _____			Matrix: _____		
Facility ID: 212177	Sample ID: 632140	Sample Name: Spaulding, Margaret 8 WS01		Sample Date: 09/01/2021	
Collection Point: Soil	Matrix: WATER	Pre Post: Remediation			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2109055-01		

Batch ID: 95132		Document Name: Size of file in bytes: 95232		File Name: Spaulding, Margaret 8 Soil Sample (2).xls	
SampleType: _____			Matrix: _____		
Facility ID: 212177	Sample ID: 632136	Sample Name: Spaulding, Margaret 8 SS02		Sample Date: 09/01/2021	
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2109055-04		

Batch ID: 95133		Document Name: Size of file in bytes: 95744		File Name: Spaulding, Margaret 8 Soil Sample (3).xls	
SampleType: _____			Matrix: _____		
Facility ID: 212177	Sample ID: 632137	Sample Name: Spaulding, Margaret 8 SS03		Sample Date: 09/01/2021	
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2109055-05		

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	06/12/2023
Total: 1 comment(s)		