

Inspection Photos
Location Name: Muegge Hand 41-31#1
Location ID: 319894



Photo#1 Production Tank



Photo#2 Gas Meter

Inspection Photos
Location Name: Muegge Hand 41-31#1
Location ID: 319894



Photo#3 Separator



Photo#4 Produced Water Tank/**NO BBL Markings**

Inspection Photos
Location Name: Muegge Hand 41-31#1
Location ID: 319894



Photo#5 Wellhead