

Inspection Photos
Location Name: State Antelope 14-24 PAD
Location ID: 428055



Photo 1 – Tank Battery

Photo 2 – Separators

Inspection Photos Shares berm with the Crude Oil Tanks



Photo 3 – ECDs



Photo 4 – Separators

Inspection Photos Shares berm with the Crude Oil Tanks



Photo 5 – Tank Battery



Photo 6 – Tank Battery Signs

Inspection Photos Shares berm with the Crude Oil Tanks



Photo 7 – Tank Battery Signs

Photo 8 – 14-11-24 HZ Wellhead – Sign Missing

Inspection Photos Shares berm with the Crude Oil Tanks



Photo 9 – 14-11-24 HZ Wellhead – Sign Missing



Photo 10 – Wellheads