

Operator: 8 NORTH LLC
Location Name: WILSON PC GQ 02-04
Loc ID: 417766
Inspection: 696304968




Exhibit A



Exhibit B

CA: Stained Soil and Oily Waste at Gas Engine. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Identified stained soil and oily waste at Gas Engine has been properly addressed. Operator has disposed of stained soil and replaced it with fresh soil to comply with Rule 905.e. The Operator will also appropriately review and properly maintain the mechanical conditions of the facility to remain in compliance with Rule 608.e.