

**Operator: 8 NORTH LLC**


**Location Name: FABRIZIUS-611N61W 33SEW**

**Loc ID: 410057**

**Inspection: 696304935**



**Exhibit A**



**Exhibit B**

**CA:** Stained Soil at Gas Engine; For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

**CA Resolution:** Identified stained soil at Gas Engine has been properly addressed. Operator has disposed of stained soil and replaced it with fresh soil to comply with Rule 905.e.