

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location #334269



SE Corner of Location – Photo #04332



NE Corner of Location – Photo #04333

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location #334269



NW Corner of Location – Photo #04334



SW Corner of Location – Photo #04335

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location #334269



Wellheads/Weeds – Photo #04343



Separator/Weeds – Photo #04338

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location #334269



Separator/Weeds – Photo #04339



Tank Battery/Weeds/Missing Battery Sign – Photo #04336

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location #334269




Tank Battery/Weeds/Missing Battery Sign – Photo #04340



Unused Equipment – Photo #04342

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location #334269



Inaccurate Information on Tank Label – Photo
#04337



Inaccurate Information on Tank Label – Photo
#04341

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location #334269



Lack of Stabilization on Access Road – Photo #04346



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04348