

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083



Photo # 54 From entrance to location



Photo # 55 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083



Photo # 56 Location



Photo # 57 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad

Location ID: 335083



Photo # 58 Location



Photo # 71 Stained soils & gravel inside GUCCINI 41C wellhead cellar

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 72 Stained soils & gravel inside GUCCINI 41C wellhead cellar



Photo # 79 Improperly marked deadman

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 80 Meter calibration info not conspicuously posted



Photo # 81 Meter calibration info not conspicuously posted