

Inspection Photos
Location Name: LAURDISON 42-8
Location ID: 320195



Photo# 1 Tanks.

Photo# 2 Meter & Separator.

Inspection Photos
Location Name: LAURDISON 42-8
Location ID: 320195



Photo# 3 Well head.

Photo# dead vegetation looking east to the location.

Inspection Photos
Location Name: LAURDISON 42-8
Location ID: 320195



Photo# Dead vegetation looking west at the well head.

Photo#2 video of gas leak in field.