

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Access road to location



Equipment leaks and stained soil

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Debris and leaking equipment



Debris and stained soils

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Tank battery signs



Debris

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Stained soil from leaking equipment




Pot drained on equipment and ground

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Leaking line and stained soil



No gas meter calibration visibly displayed

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Erosion and sediment migration from location



Erosion and sediment migration from location

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Erosion and sediment migration from location



Lack of stabilization and vehicle tracking

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Location view from entrance and Northeast corner



Location view from Northwest corner

**KT Resources LLC
WRD Federal 19-11
Location #316277**



Location view from Southwest corner



Location view from Southeast corner