

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 326 From entrance to location



Photo # 327 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 328 From entrance to location



Photo # 333 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 334 Location



Photo # 335 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 347 Meter calibration info not conspicuously posted



Photo # 348 Unused Equipment – ECD is disconnected & not operational

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



**Photo # 349 Unused Equipment – ECD is disconnected & not operational**



**Photo # 350 Unused Equipment – ECD is disconnected & not operational**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 352 Debris



Photo # 353 Debris

Inspection Photos  
Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad  
Location ID: 336023



Photo # 354 Debris

Photo # 364 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 366 Debris



Photo # 362 Improperly marked deadman

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 358 Containment needs maintenance



Photo # 359 Containment needs maintenance

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



**Photo # 355 Containment needs maintenance**