

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #324270




SE Corner of Location – Photo #04380



NE Corner of Location – Photo #04381

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #324270



NW Corner of Location – Photo #04382



SE Corner of Location – Photo #04383

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #324270



Wellhead/Weeds/Missing Wellhead Sign – Photo #04384



Separator/Gas Meter/Weeds – Photo #04385

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #324270



Tank Battery/Weeds – Photo #04387



Rill Erosion Transporting Sediment Off-Location – Photo #04391

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #324270



Location Lacks Stabilization – Photo #04393



Rill Erosion Transporting Sediment from Access Road to Drainage Ditch – Photo #04398

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #324270



Rill Erosion Transporting Sediment from Access Road to Drainage Ditch – Photo #04399



Access Road Lacks Stabilization – Photo #04400

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #324270



Access Road Lacks Stabilization – Photo #04401



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04402