

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #312598



NW Corner of Location – Photo #04366



NE Corner of Location – Photo #04367

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #312598



SE Corner of Location – Photo #04368



SW Corner of Location – Photo #04369

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #312598



Wellhead/Weeds – Photo #04374



Separator/Gas Meter/Weeds – Photo #04373

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #312598



Tank Battery/Weeds – Photo #04371



Debris – Photo #04375

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #312598



Debris – Photo #04377



Debris – Photo #04378

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location #312598



Access Road Lacks Stabilization – Photo #04401



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04402