

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2023

Submitted Date:

06/15/2023

Document Number:

707601373

FIELD INSPECTION FORMLoc ID 302619 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299704	WELL	TA	04/28/2020	OW	123-29488	WELLS RANCH USX AA 23 -09	TA

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.

Abandoned Centralized Battery formerly served 4 Location IDs
(302619, 310042, 302620, 310043).
(Well(s): 2: Temporarily Abandoned | TA ; 2: Plugged & Abandoned | PA).
Abandoned Battery SE corner GPS coordinates: 40.468904 / -104.398991

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	
Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Temporarily Abandoned TA. Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Temporarily Abandoned TA. Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Temporarily Abandoned TA. Battery Abandoned. Equipment removed.		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment: Temporarily Abandoned TA. Battery Abandoned. Equipment removed.						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment: Temporarily Abandoned TA. Battery Abandoned. Equipment removed.						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 299704 Type: WELL API Number: 123-29488 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI tag posted.
COGCC records last production: 11/2016.
SI/TA well per variance doc. #401474555. (NOBLE).

Form 4 on file. TA date: 09/20/2018. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 11/01/2016. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/17/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 06/15/2023 at approximately 11:20 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH USX AA-66N63W/23NESE Location ID: 302619 Well Name(s): Wells Ranch USX AA 23-09. API: 123-29488. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed.</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (302619, 310042, 302620, 310043). (Well(s): 2: Temporarily Abandoned TA ; 2: Plugged & Abandoned PA). Abandoned Battery SE corner GPS coordinates: 40.468904 / -104.398991</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/15/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601374	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6149634