

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Jun 12, 2023 at 1:06:06 PM



Jun 12, 2023 at 1:06:10 PM

Photo # 197 From entrance to location

Photo # 198 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 199 Location



Photo # 200 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 201 Location

Photo # 213 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 214 Debris



Photo # 216 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 218 Weeds/undesirable plant species



Photo # 220 Weeds/undesirable plant species

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



**Photo # 221 Weeds/undesirable plant species**

**Photo # 222 Weeds/undesirable plant species**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 223 Weeds/undesirable plant species



Photo # 224 Weeds/undesirable plant species

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 225 Weeds/undesirable plant species



Photo # 226 Weeds/undesirable plant species

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972




Photo # 227 Weeds/undesirable plant species



Photo # 228 Weeds/undesirable plant species

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 233 Weeds/undesirable plant species



Photo # 234 Weeds/undesirable plant species

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



Photo # 240 Weeds/undesirable plant species



Photo # 236 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



**Photo # 231 Hole in base of liner/containment needs maintenance**



**Photo # 232 Hole in base of liner/containment needs maintenance**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 22-22 Pad

Location #: 420972



**Photo # 261 Meter calibration info not conspicuously posted**

**Photo # 262 Meter calibration info not conspicuously posted**