

Interim and Stormwater Inspection

May 30,, 2023

Operator: Petro Canada Resources # 72085

Location ID: 311698

Inspection Document #:709400287

Adams, County

NESW, Section 13, 3S59W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Upper Noonan 2-B
Location ID: 311698



Photo 1. Photo taken of bare areas in reclaimed area.

Photo 2. photo of sparsely vegetated area in reclaimed area.



Inspection Photos
Location Name: Upper Noonan 2-B
Location ID: 311698



Photo 3. Photo taken of weeds (cheatgrass) on site.

Photo 4. Photo taken of weeds and bare areas in the reclaimed area.