

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 525 From entrance to location



Photo # 526 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 527 Location



Photo # 528 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 529 Location



Photo # 530 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 539 Location




Photo # 534 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 535 Meter calibration info not conspicuously posted



Photo # 536 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 537 Meter calibration info not conspicuously posted



Photo # 531 Debris



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 532 Debris



Photo # 542 Unused equipment/ECD is disconnected



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 543 Unused equipment/ECD is disconnected