

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 487 From entrance to location



Photo # 488 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 489 Location



Photo # 490 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Jun 15, 2023 at 9:15:40 AM
CO



Jun 15, 2023 at 9:16:13 AM
CO

Photo # 491 Location

Photo # 492 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad
Location #: 336015



Photo # 494 Meter calibration info not conspicuously posted




Photo # 495 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 501 Unused equipment



Photo # 514 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 515 Same unmarked deadman from a different vantage point.