

# Inspection Photos

Loc: 325591

Operator: SIMCOE LLC

Inspection Date: 6/15/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 1.** Sign is posted at entrance of location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 2.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 3.** Facing toward the buried tank. There are noxious weeds at the location that need to be controlled. Red arrow points to Musk thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 4.** Facing southeast along the flowline. There are noxious weeds along the flowline that need to be controlled. Red arrow points to Canada thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 5.** Facing southeast along the flowline shown at red arrow. There are noxious weeds along the flowline that need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 6.** Facing south where flowline riser is located approximately 650 ft. southeast from the location. Flowline then travels northeast and southwest.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 7.** Facing northeast from previous photo. There are noxious weeds along this area and there are areas bare of vegetation that need to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023

## Inspection Photos



**Photo 8.** Facing north toward the buried tank southwest of the location at Lat/Long 37.17695,-107.76227.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325591 | Date: 6/15/2023