

Operator: EXTRACTION OIL & GAS INC

Location Name: Rubyanna 13 Pad

Loc ID: 436071

Inspection: 679605657



Exhibit A



Exhibit B

CA: Two buckets near pumpjacks. Comply with Rule 606.

CA Resolution: Location has been cleared/cleaned of identified trash and debris to comply with Rule 606.



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Stained soil at pumpjack. Conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002.(2).d.

CA Resolution: Identified stained soil at the pumpjack has been properly addressed. Operator has disposed of stained soil and cleaned the area, as well as equipment/signs on location. Operator will continue to monitor and maintain equipment appropriately to remain in compliance with Rule 1002.(2).d.

dcp
Midstream.

Station Number	218285	
Station Name	Rubyanna CTR-2	
Static Range	0-500 [#]	
Calibrated Static Span	0-500 [#]	
Differential Range	0-250 ^V	
Calibrated Diff. Span	0-250 ⁿ	
Temperature Range	0-200 ^o	
Meter Run Size	3.273	
Legals		
Date	Orifice Size	Test Date
9-10-20	1.000	9-15-21
2-3-23	1.000	2-3-23am

Exhibit A

CA: Meter does not appear to be annually calibrated. Calibrate gas metering equipment annually to comply with rule 430.d.(1).

CA Resolution: Operator has provided updated meter card to reflect annual calibration to comply Rule 430.d.(1)