

Inspection Photos

API: 067-07028

Operator: SIMCOE LLC

Inspection Date: 6/15/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 1. Facing northwest along the access road. There is vehicle rutting and tracking along the road that needs to be repaired and stabilized. There are also noxious weeds along the roadside that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 2. Facing northwest along the access road. There is vehicle rutting and tracking along the road that needs to be repaired and stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 3. Facing northwest along the access road. This area had previously washed out and was repaired however, stormwater is directed down this area and there are no BMP's to divert off the road e.g. culvert water bar ect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 4. Facing east toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 5. There is oil stained soils outside of containment at the buried tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 6. There are stain soils inside containment that need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 7. There is vehicle ruts where stormwater accumulates which need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023