

Operator: EXTRACTION OIL & GAS INC
Location Name: DIAMOND VALLEY EAST
Loc ID: 435083
Inspection: 679605652



Exhibit A



Exhibit B

CA: One tank has faded labeling. One tank does not display labeling. Install sign to comply with Rule 605.h.

CA Resolution: Signage/Labels have been installed appropriately to comply with Rule 605.h.



Exhibit A



Exhibit B

CA: Unused equipment on various areas of location. Comply with Rule 606.

CA Resolution: Identified unused equipment has been addressed and removed to comply with Rule 606.