

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Jun 15, 2023 at 10:28:00 AM  
CO



Jun 15, 2023 at 10:29:04 AM  
CO

Photo # 572 From entrance to location

Photo # 574 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 575 Location



Photo # 576 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 577 Location



Photo # 578 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 584 Meter calibration info not conspicuously posted



Photo # 585 Meter calibration info not conspicuously posted



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



**Photo # 586 Meter calibration info not conspicuously posted**



**Photo # 588 Meter calibration info not conspicuously posted**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



**Photo # 594 Unused equipment - ECD is disconnected**



**Photo # 595 Unused equipment - ECD is disconnected**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038




Photo # 587 Debris



Photo # 588 Debris



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 598 Debris