

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH C Pad

Location #: 336028



Photo # 550 From entrance to location



Photo # 551 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH C Pad

Location #: 336028



Photo # 552 Location



Photo # 553 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH C Pad

Location #: 336028



Jun 15, 2023 at 10:10:00 AM
CO



Jun 15, 2023 at 10:10:26 AM
CO

Photo # 554 Location

Photo # 555 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH C Pad

Location #: 336028



Photo # 563 Meter calibration info not conspicuously posted



Photo # 564 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH C Pad

Location #: 336028



Photo # 567 Open ended load line



Photo # 568 Open ended load line