

# TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

## Location #324116



**SW Corner of Location – Photo #04483**



**NW Corner of Location – Photo #04484**

# TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

## Location #324116



**NE Corner of Location – Photo #04485**



**SE Corner of Location – Photo #04486**



# TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

Location #324116



Wellhead – Photo #04487



Separators – Photo #04490



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



# TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

Location #324116



Tank Battery – Photo #04496



Rill Erosion Transporting Sediment onto Location –  
Photo #04491



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



# TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

Location #324116



**Rill Erosion Transporting Sediment onto Location –  
Photo #04494**



**Rill Erosion Transporting Sediment onto Location –  
Photo #04495**



# TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

Location #324116



**Location Lacks Stabilization – Photo #04497**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04498**