

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 605 From entrance to location



Photo # 606 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 608 Location



Photo # 609 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Jun 15, 2023 at 10:58:16 AM  
CO



Jun 15, 2023 at 10:58:36 AM  
CO

Photo # 610 Location

Photo # 611 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 615 Meter calibration info not conspicuously posted

Photo # 616 Meter calibration info not conspicuously posted

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 621 Debris

Photo # 623 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014




Photo # 624 Debris



Photo # 607 Sign at entrance to location shows incorrect operator & contact #

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 522 Signs at entrance to access road show inaccurate emergency contact #



Photo # 523 Signs at entrance to access road show inaccurate emergency contact #