

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 871 From entrance to location



Photo # 872 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 873 Location



Photo # 874 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 875 Location



Photo # 876 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 877 Location



Photo # 879 Weeds/undesirable plant species around wellheads & chemical tanks

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 880 Weeds/undesirable plant species around wellheads & chemical tank



Photo # 892 Weeds/undesirable plant species around wellheads & chemical tank

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 913 Weeds/undesirable plant species around wellheads



Photo # 914 Weeds/undesirable plant species around wellheads



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 916 Weeds/undesirable plant species around wellheads



Photo # 919 Weeds/undesirable plant species around wellheads



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 926 Weeds/undesirable plant species in secondary containment



Photo # 927 Weeds/undesirable plant species in secondary containment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 928 Weeds/undesirable plant species in secondary containment



Photo # 929 Weeds/undesirable plant species in secondary containment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 920 Unused equipment - ECD is disconnected



Photo # 921 Unused equipment - ECD is disconnected



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Jun 16, 2023 at 11:36:41



Jun 16, 2023 at 11:37:36 AM
CO

Photo # 923 Unused equipment - ECD is disconnected

Photo # 925 Unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 934 Hole in liner/liner needs maintenance



Photo # 935 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad
Location #: 335550



Photo # 947 Meter calibration info not conspicuously posted



Photo # 948 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 939 Stained gravel

