

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 732 From entrance to location



Photo # 733 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 736 Location



Photo # 737 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Jun 16, 2023 at 9:51:10 AM  
CO



Jun 16, 2023 at 9:51:36 AM  
CO

Photo # 738 Location

Photo # 739 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



**Photo # 740 Debris around secondary containment**



**Photo # 741 Debris around secondary containment**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 742 Open ended load line



Photo # 743 Debris

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad**  
**Location #: 335549**



**Photo # 744 Stained gravel in secondary containment**

**Photo # 745 Stained gravel in secondary containment**

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad**  
**Location #: 335549**



**Photo # 750 Meter calibration info not conspicuously posted**

**Photo # 751 Meter calibration info not conspicuously posted**

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad**  
**Location #: 335549**



**Photo # 752 Meter calibration info not conspicuously posted**



**Photo # 756 Sign at entrance to location contains inaccurate information**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



**Photo # 759 Weeds/undesirable plant species around wellheads**



**Photo # 760 Weeds/undesirable plant species around wellheads**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



**Photo # 761 Weeds/undesirable plant species around wellheads**



**Photo # 762 Weeds/undesirable plant species around wellheads**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



**Photo # 764 Weeds/undesirable plant species around wellheads**



**Photo # 765 Weeds/undesirable plant species around wellheads**

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad**  
**Location #: 335549**



**Photo # 766 Weeds/undesirable plant species around wellheads**



**Photo # 767 Weeds/undesirable plant species around wellheads**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



**Photo # 768 Weeds/undesirable plant species around wellheads**



**Photo # 769 Weeds/undesirable plant species around wellheads**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



**Photo # 774 Weeds/undesirable plant species around wellheads**



**Photo # 775 Weeds/undesirable plant species around wellheads**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



**Photo # 774 Weeds/undesirable plant species around wellheads**



**Photo # 775 Weeds/undesirable plant species around wellheads**