

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: ARISTOCRAT ANGUS 2-4-8

Loc ID: 333183

Inspection: 709400293



Exhibit A



Exhibit B

CA: Old concrete on location in reclaimed pipeline right of way. Comply with Rule 606.d.

CA Resolution: Location has been cleaned and cleared of trash and debris (identified concrete) to comply with Rule 606.d. It is important to note that Operator has reported that landowner has been disposing of horse manure on one of the flowline sections.



Exhibit A



Exhibit B

CA: Weeds starting to emerge on pipeline right of way, in disturbed areas. Comply with Rule 606.c.

CA Resolution: Operator has addressed the emerging weeds and will monitor the location to manage weeds appropriately to comply with Rule 606.c.



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J



Exhibit K



Exhibit L



Exhibit M

CA: Soil erosion accruing in disturbed areas of pipeline right of way, from removal of flowlines. Recent rains have caused run on into reseeded areas below culvert. Comply with Rule 1002.f.

CA Resolution: Operator has effectively addressed the soil erosion issue by installing appropriate support, stabilizing/protecting vulnerable areas of the location, properly cleaning the area, and reseeded as needed. Location will be managed and maintained to comply with Rule 1002.f.