

Inspection Photos

API: 067-08323

Operator: SIMCOE LLC

Inspection Date: 6/14/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 067-08323 | Date: 6/14/2023

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-08323 | Date: 6/14/2023

Inspection Photos



Photo 2. Facing toward the east fill slope which appears stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-08323 | Date: 6/14/2023

Inspection Photos



Photo 3. There are noxious weeds along the south fill slope that need to be controlled. Red arrow points to Canada thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-08323 | Date: 6/14/2023