

# Inspection Photos

API: 067-07031

Operator: HILCORP ENERGY COMPANY

Inspection Date: 6/14/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 067-07031 | Date: 6/14/2023

## Inspection Photos



**Photo 1.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 067-07031 | Date: 6/14/2023

## Inspection Photos



**Photo 2.** There is oil stained soils that need to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 067-07031 | Date: 6/14/2023

## Inspection Photos



**Photo 3.** Stained soils were also observed near the engine compressor where the leak appeared to had come from.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 067-07031 | Date: 6/14/2023