

Inspection Photos

API: 067-07059

Operator: SIMCOE LLC

Inspection Date: 6/14/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 067-07059 | Date: 6/14/2023

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-07059 | Date: 6/14/2023

Inspection Photos



Photo 2. Facing toward the south fill slope which appears stabilized with vegetation. There are noxious weeds in this area that need to be controlled. Red arrow points to Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-07059 | Date: 6/14/2023