

Inspection Photos

API: 067-08378

Operator: SIMCOE LLC

Inspection Date: 6/14/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 326601 | Date: 6/14/2023

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 326601 | Date: 6/14/2023

Inspection Photos



Photo 2. Facing toward the cut slope which appears stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 326601 | Date: 6/14/2023

Inspection Photos



Photo 3. There are some noxious weeds along the cut slope that need to be controlled. Also there are numerous t-posts fences that do not appear to be in use (e.g. no shrubs or trees inside).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 326601 | Date: 6/14/2023

Inspection Photos



Photo 4. There are some noxious weeds along the cut slope that need to be controlled. Also there are numerous t-posts fences that do not appear to be to be in use (e.g. no shrubs or trees inside).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 326601 | Date: 6/14/2023

Inspection Photos



Photo 5. Facing toward the fill slope.

