

**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**



**Photo 1 – Pumping unit**



**Photo 2 – Wellhead Sign**

**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**




**Photo 3 – Wellhead**




**Photo 4 – Pumping Unit**



**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**



**Photo 5 – Unmarked Risers**



**Photo 6 – Unmarked Risers**

**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**



**Photo 7 – Back Drain Leaking**




**Photo 8 – Back Drain Leaking**



**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**




**Photo 9 – Unmarked Risers**




**Photo 10 – Unused Parts**



**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**



**Photo 11 – Unused Valve**



**Photo 12 – Unmark Risers**

**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**




**Photo 13 – Unmarked Riser**




**Photo 14 – Gas Meter**



**Inspection Photos**  
**Location Name: Lost Creek #1**  
**Location ID: 323364**



**Photo 15 – Tagged out by Gas Operator**



**Photo 16 – Valve appears in the Closed position**