

Final Reclamation and Stormwater Inspection

Date: 06/14/2023

Operator: PCR OPERATING LLC - 10657

Location ID: 313705

Inspection Document #: 708200315

Morgan County, CO

SWNW Section 13 T1N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Crone, B F-61N58W
Location ID: 313705



Photo 1. At the time of this inspection, Staff observed that bare soil and debris remain on location; this was also documented in inspections #682504409, #969200044, and #696200381. Additionally, Colorado List C Noxious Weed (e.g. cheatgrass) and other undesirable species (e.g. kochia) were observed to be growing throughout the location and will need to be managed for. This location does not appear to be progressing towards Rule 1004 standards.

Inspection Photos
Location Name: Crone, B F-61N58W
Location ID: 313705



Photo 2. See comments in Photo 1. Red outline indicates Colorado List C Noxious Weed (e.g. cheatgrass)

Inspection Photos
Location Name: Crone, B F-61N58W
Location ID: 313705



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Crone, B F-61N58W
Location ID: 313705



Photo 4. See comments in Photo 1.

Inspection Photos
Location Name: Crone, B F-61N58W
Location ID: 313705



Photo 5. Close up of debris observed on location.