

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900



Photo # 1138 From entrance to location



Photo # 1140 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900



Photo # 1141 Location



Photo # 1144 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900



Photo # 1142 Location



Photo # 1143 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900



Photo # 1153 Unused equipment



Photo # 1156 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900




Photo # 1157 Debris & Unused equipment



Photo # 1159 Debris

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900



Photo # 1162 Debris

Photo # 1163 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900



Photo # 1165 Unused equipment



Photo # 1173 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad

Location #: 413900



Photo # 1158 Tank label missing required information



Photo # 1168 Tank label missing required information

Location Name: TEP ROCKY MOUNTAIN LLC CB TRACT 10 Pad  
Location #: 413900



Photo # 1160 Stained gravel



Photo # 1161 Stained gravel