




WELLHEAD ABANDONMENT FORM

SITE NAME: Howard 25C-35HZX							DATE: 6/12/2023	REM. PROJECT #:	WEATHER:
SITE DIRECTIONS: CR 4/ CR 21 W 0.4, N 0.1, E into							CLIENT: Oxy		
LEGALS AND LAT/LONG: 40.016225, -104.874937							TASMAN PERSONNEL: Ben Wagner		
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: North		
SOIL SAMPLING							FACILITY INFRASTRUCTURE		
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity
							Above Ground Storage Tank (AST)		
6/12/2023 09:31	WH-B01@6'	7.0	HC Staining	HC Odor	Yes	Lab	Buried or Partially Buried Vessel		
6/12/2023 09:33	WH-N01@5'	13.4	HC Staining	HC Odor	Yes	Lab	Separator		
6/12/2023 09:35	WH-S01@5'	0.0	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)		
6/12/2023 09:37	WH-E01@5'	5.2	HC Staining	HC Odor	Yes	N/A	Dump Line		
6/12/2023 09:39	WH-W01@5'	0.7	HC Staining	HC Odor	Yes	N/A	Wellhead		1
6/12/2023 09:41	WHS-N01@3"	0.1	No Staining	No Odor	Yes	N/A	Flowline		1
6/12/2023 09:43	WHS-S01@3"	0.0	No Staining	No Odor	Yes	N/A	Other:		
6/12/2023 09:45	WHS-E01@3"	0.0	No Staining	No Odor	Yes	N/A	Soil Loads Removed		
6/12/2023 09:47	WHS-W01@3"	0.2	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?		
6/12/2023 09:51	BG01@3'	0.0	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:		
6/12/2023 09:53	BG01@6'	0.0	No Staining	No Odor	Yes	Lab	Date	Number	CY
6/12/2023 09:55	BG02@3'	0.0	No Staining	No Odor	Yes	Lab			
6/12/2023 09:57	BG02@6'	0.0	No Staining	No Odor	Yes	Lab			
6/12/2023 09:59	FL-B01@4'	0.0	No Staining	No Odor	Yes	Lab			
6/13/2023 10:30	FL-B02@4'	0.0	No Staining	No Odor	Yes	Lab			
							Total Removed		0 0
							Disposal Facility:		
							Groundwater Recovery		
							DATE GW ENCOUNTERED:		DEPTH:
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?		
							LNAPL OR SHEEN OBSERVED ON GW?		
GROUNDWATER SAMPLING							Date		BBLs
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?			
							Total Removed		0
							Disposal Facility:		

Photographic Log

					
Equipment ID:		Equipment Type:	Equipment ID:		Equipment Type:
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions:			Notes/Conditions: Visible water in excavation area is due to rain.		

Photographic Log



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Visible water in excavation area is due to rain.			