

Interim Reclamation and Stormwater Inspection

May 11, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697504724

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 1. Photo taken from the southern location, facing West. Red arrow is pointing at new growth (green vegetation). COGCC believes this to be an introduced grass species which was not accurately reported to COGCC.



Photo 2. Photo taken from the southern location, facing North. Photo illustrates much of the new growth to be an introduced grass species. See comments under Photo 1.

Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 3. Photo taken from the southeastern perimeter of location, facing North. Red polygon illustrates the approximate area with a List B Colorado noxious weed, Canada thistle.



Photo 4. Close up photo taken of some Canada thistle.



Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 5. Photo taken from the topsoil stockpile, facing West. Photo illustrates the topsoil stockpile remains unstabilized and no desirable vegetative growth. Weedy annual growth is starting to establish.

