

# Final Reclamation and Stormwater Inspection

Date: 06/14/2023

Operator: KLABZUBA OIL & GAS INC - 10148

Location ID: 393690

Inspection Document #: 708200317

Morgan County, CO

SWNE Section 12 T1N R58W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 1.** From the start of the former access road. The access road does not appear to be progressing towards Rule 1004 standards with areas of bare soil and undesirable vegetation (e.g. kochia) observed.

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 2.** Approximate midpoint of the access road. See comments in Photo 1.

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 3.** Debris observed on the former access road.

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 4.** The former well location does not appear to be progressing towards Rule 1004 standards with areas of bare soil and undesirable vegetation (e.g. kochia) observed. Some desirable vegetation was observed interspersed throughout the reclaimed area (e.g. sand dropseed and western wheat) but overall is not reflective of reference areas.

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 5.** See comments in Photo 4.

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 6.** See comments in Photo 4.

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 7.** See comments in Photo 4.

Inspection Photos  
Location Name: COEN, M E-61N58W  
Location ID: 393690



**Photo 8.** Reference area is predominantly western wheat.