

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-15A.

Location ID: 413541



Photo #367 From entrance to location.



Photo #368 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-15A.

Location ID: 413541



Photo #370 Multiple laces with unused equipment.



Photo #372 Multiple places with unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-15A.

Location ID: 413541



Photo #373 Stained soils and gravel.



Photo #374 Calibration cards not consciously posted.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources