

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Furr /A-11 Pad

Location ID: 335027



Photo #410 From entrance to location.



Photo #411 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Furr /A-11 Pad

Location ID: 335027



Photo #412 Calibration cards not conspicuously posted.



Photo #413 Unused tanks.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Furr /A-11 Pad

Location ID: 335027



Photo #414 Unused tank.



Photo #416 unused tanks.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Furr /A-11 Pad

Location ID: 335027



Photo #417 Unused tanks.



Photo #418 Unused tanks.