

Interim Reclamation and Stormwater Inspection

June 15, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462908

Inspection Document #: 697504726

Weld County, CO

NESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 1. Photo taken from the southeastern location, facing North. Photo illustrates interim reclamation has been performed; however, interim reclamation is not complete due to the lack of soil stabilization. Erosion was evidence and much of the interim reclamation area had no desirable establishment.



Photo 2. Photo taken from the southeastern location, facing West. Photo illustrates erosion and no soil stabilization.

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 3. Photo taken from the eastern interim reclamation area, facing North. See comments under Photo 1.



Photo 4. Photo taken from the north central interim reclamation area, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 5. Photo taken from the western interim area, facing East. Photo illustrates straw mulch that appears to be staged for soil stabilization.



Photo 6. Photo taken from the topsoil stockpile, facing East. Photo illustrates the topsoil stockpile which has been seeded; however, the topsoil stockpile lacks soil stabilization. Some germination of desirable establishment was observed but again lacks soil stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504726