

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905

Date: 6/21/2023



SW Corner of Location – Photo #04581



NW Corner of Location – Photo #04582

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905

Date: 6/21/2023



NE Corner of Location – Photo #04583



SE Corner of Location – Photo #04584

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905

Date: 6/21/2023



Wellheads – Photo #04585

Separators – Photo #04590



TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905

Date: 6/21/2023



Tank Battery – Photo #04592



Access Road Ditch Full of Sediment/Needs Maintenance – Photo #04587

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905

Date: 6/21/2023



**Rill Erosion Transporting Sediment Off Location –
Photo #04589**

**Rill Erosion Transporting Sediment Off Location –
Photo #04588**

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905

Date: 6/21/2023



**Rill Erosion on Access Road/Insufficient Vehicle Tracking
BMPs at Location Entrance/Exit – Photo #04591**