

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location #334871

Date: 6/19/2023



SW Corner of Location – Photo #04607



NW Corner of Location – Photo #04608

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location #334871

Date: 6/19/2023



NE Corner of Location – Photo #04609



SE Corner of Location – Photo #04610

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location #334871

Date: 6/19/2023



Wellheads – Photo #04611



Separators – Photo #04613



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location #334871

Date: 6/19/2023



Tank Battery – Photo #04614



Debris on West End of Location – Photo #04620



TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location #334871

Date: 6/19/2023



**Open-Ended Load Line on Produced Water Tank –
Photo #04617**



**Open-Ended Load Line on Condensate Tank – Photo
#04618**

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location #334871

Date: 6/19/2023



Location Lacks Stabilization – Photo #04621



Location Lacks Stabilization – Photo #04622

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location #334871

Date: 6/19/2023



Location Lacks Stabilization – Photo #04623



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04625