

# Final Reclamation Inspection

June 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 331067

Inspection Document #: 701900888

NWSE Section 9 5N 67W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Edwards 33-9  
Location ID: 331067



**Photo 1.** 2021 aerial imagery of the well pad and access road. Note: Tank battery highlighted in blue remains for the Edwards 43-9 well API #123-20867.

Inspection Photos  
Location Name: Edwards 33-9  
Location ID: 331067



**Photo 2.** Overview photo of the well pad taken at ground level from the eastern edge facing west.



Inspection Photos  
Location Name: Edwards 33-9  
Location ID: 331067



**Photo 3.** Close up photo of vegetation density within well pad (Triticale and kochia are the dominant species).





Inspection Photos  
Location Name: Edwards 33-9  
Location ID: 331067



**Photo 4.** Overview and close up photo of well pad reference area. Vegetation density and plant community appear consistent with well pad disturbance.



Inspection Photos  
Location Name: Edwards 33-9  
Location ID: 331067



**Photo 5.** Overview photo of the access road taken at ground level from the eastern edge facing west. Note: access road does not appear consistent with adjacent reference area (see photo #4).



Inspection Photos  
Location Name: Edwards 33-9  
Location ID: 331067



**Photo 6.** Tank battery remains for the Edwards 43-9 well API # 123-20867.