

Final Reclamation Inspection

June 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 332813

Inspection Document #: 701900890

NWSE Section 10 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



Photo 1. 2021 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



Photo 2. Overview photo of the well pad taken at ground level from the northern edge facing south.

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



Photo 4. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: well pad falls within a wasteland/prairie dog area and appears consistent with adjacent reference area (see photo #).

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



Photo 5. Overview photo of the tank battery taken at ground level from the eastern edge facing west.

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



Photo 6. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



Photo 7. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery has higher density of perennial vegetation compared to adjacent reference area (see photo #8).

Inspection Photos
Location Name: Wolf 44-31
Location ID: 332813



2023/06/01
309' 1"u
E27 W: 515861.0
N: 4457350.0

Photo 8. Reference area.