

# Final Reclamation Inspection

June 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 328429

Inspection Document #: 701900892

SESW Section 20 T5N R64W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Evert 20-2  
Location ID: 328429



**Photo 1.** 2019 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos  
Location Name: Evert 20-2  
Location ID: 328429



**Photo 2.** Overview photo of the well pad, access road and reference area taken with a drone from the northern edge facing south. Note: well pad and access road appear consistent with adjacent crop reference area.



Inspection Photos  
Location Name: Evert 20-2  
Location ID: 328429



**Photo 3.** Overview photo of the tank battery taken at ground level from the western edge facing east. Note: tank battery falls within a corner crop area and appears consistent with reference corner crop (see photo #4).

Inspection Photos  
Location Name: Evert 20-2  
Location ID: 328429



**Photo 4.** Tank battery reference area.

