

# Final Reclamation Inspection

June 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 333292

Inspection Document #: 701900896

NWSE Section 10 T4N R67W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Totems 34-24  
Location ID: 333292



**Photo 1.** 2022 aerial imagery of the well pad. Note: could not identify access road from historic imagery. Tank battery highlighted in blue remains for the producing Lawrence Totem 2 well, API #123-08485.

Inspection Photos  
Location Name: Totems 34-24  
Location ID: 333292



**Photo 2.** Overview photo of the well pad and reference area taken with a drone from the southern edge facing north. Note: well pad appears consistent with adjacent crop reference area.

Inspection Photos  
Location Name: Totems 34-24  
Location ID: 333292



**Photo 3.** Overview ground photo of the well pad crop field.