

Final Reclamation Inspection

May 31st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 319112

Inspection Document #: 701900910

NWNE Section 27 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Urich Don 31-27
Location ID: 319112



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos
Location Name: Urich Don 31-27
Location ID:319112



Photo 2. Overview photo of the well pad and access road taken at ground level from the northern edge facing south looking down the access road.

Inspection Photos
Location Name: Urich Don 31-27
Location ID:319112



Photo 2. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Urich Don 31-27
Location ID:319112



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad is dominated by cheatgrass and does not appear consistent with adjacent reference area (see photo #4).

Inspection Photos
Location Name: Urich Don 31-27
Location ID:319112



Photo 4. Well pad reference area to the south of the disturbance.

Inspection Photos
Location Name: Urich Don 31-27
Location ID:319112



Photo 5. Overview photo of the tank battery. Note: tank battery falls within a storage area of ARB Midstream company.