

Final Reclamation Inspection

May 31st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 322552

Inspection Document #: 701900911

SENE Section 30 T7N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Eaton CC #1
Location ID: 322552



Photo 1. 2021 aerial imagery of the well pad and tank battery. Note: well pad is on a golf course.

Inspection Photos
Location Name: Eaton CC #1
Location ID:322552



Photo 2. Overview photo of the well pad taken at ground level from the southern edge facing north.



Inspection Photos
Location Name: Eaton CC #1
Location ID:322552



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge facing west.

Inspection Photos
Location Name: Eaton CC #1
Location ID:322552



Photo 3. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Eaton CC #1
Location ID:322552



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery appears consistent with adjacent reference area (see photo #5).

Inspection Photos
Location Name: Eaton CC #1
Location ID:322552



Photo 5. Tank battery reference area.

